

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
4-BALT,
178A-

W. Lexington St., Murphy Building
(Murphy Building)
(Hochschild-Kohn Annex)
320-322 W. Lexington St.
Baltimore
Maryland

HABS No. MD-77-A

Russell Wright, Photographer 1977

- MD-77-A-1 EXTERIOR, SOUTH FRONT, UPPER LEVELS (2 1/4" x 2 3/4" negative)
- MD-77-A-2 EXTERIOR, SOUTH FRONT, FOURTH, FIFTH AND SIXTH FLOORS (2 1/4" x 2 3/4" neg.)
- MD-77-A-3 EXTERIOR, SOUTH FRONT, SECOND FLOOR, PILASTER ON
LEFT SIDE OF FACADE (2 1/4" x 2 3/4" neg.)
- MD-77-A-4 EXTERIOR, SOUTH FRONT, DETAIL OF SECOND FLOOR PILASTER
ON RIGHT SIDE OF FACADE (35mm negative)
- MD-77-A-5 EXTERIOR, SOUTH FRONT, SECOND FLOOR CORNICE (35mm negative)
- MD-77-A-6 EXTERIOR, THIRD AND FOURTH FLOORS SHOWING CORNICE,
WINDOWS AND DECORATIVE PILASTERS (35mm negative)
- MD-77-A-7 EXTERIOR, SOUTH FRONT, FOURTH FLOOR (35mm negative)
- MD-77-A-8 EXTERIOR, SOUTH FRONT, FOURTH FLOOR, DETAIL OF PILASTER
WITH TERRA COTTA APPLIED DECORATION (35mm negative)
- MD-77-A-9 EXTERIOR, SOUTH FRONT, FIFTH FLOOR, DETAIL OF ARCH (35mm negative)
- MD-77-A-10 EXTERIOR, SOUTH FRONT, SIXTH FLOOR AND CORNICE (35mm negative)
- MD-77-A-11 EXTERIOR, SOUTH FRONT, DETAIL OF ROOF CORNICE (35mm negative)
- MD-77-A-12 INTERIOR, FIFTH FLOOR, VIEW LOOKING OUTSIDE SHOWING
WROUGHT IRON RAILING (2 1/4" x 2 3/4" negative)